

ILC LightLEEDer Tools

- Version 1.21 26-Oct-2020
Bluetooth configuration and test functions added to G3 configure/test screen
- Version 1.22 04-Dec-2020
Bluetooth configuration tool modified due to a configuration failed error
- Version 1.23 10-Dec-2020
Modifications for updated Windows 10 USB port driver timing
- Version 1.24 01-Dec-2021
Added Bluetooth power configuration to ensure highest setting
- Version 1.25 05-Dec-2021
Removed Bluetooth power configuration after finding it was not needed
Bluetooth connection test now based on BTA rather than ID
- Version 1.29 08-Dec-2021
Timing and command strings adjusted to allow for more connection time
- Version 1.31 09-Dec-2021
Timing for Bluetooth connection optimized
- Version 1.32 16-Feb-2022
Dual tech occupancy sensor monitor and PIR configuration tool added
Note: Dual tech support hidden until a right click on an open area of the main screen
- Version 1.33 16-Dec-2022
Wireless tools incorporated into one tools package
Setup program created
- Version 1.34 23-Jan-2023
Display show dimmer values for wireless relays
Silicon Labs USB drivers removed from setup program
- Version 1.35 29-Jan-2023
Added Discover Network Panel Addresses function
- Version 1.36 20-Jul-2023
Added DT ceiling sensor tool
- Version 1.37 23-Aug-2023
DT ceiling sensor tool screen uses default settings each time window is opened
- Version 1.38 24-Aug-2023
On DT sensor screen
-Changed PIR and acoustic sensitivity order from Low/Mid/High to Low/High/Mid
-Added device configuration options
- Version 1.39 11-Oct-2023
Wireless tools removed and new setup program created