## ILC LightLEEDer Tools

Version 1.21 26-Oct-2020

Bluetooth configuration and test functions added to G3 configure/test screen

Version 1.22 04-Dec-2020

Bluetooth configuration tool modified due to a configuration failed error

Version 1.23 10-Dec-2020

Modifications for updated Windows 10 USB port driver timing

Version 1.24 01-Dec-2021

Added Bluetooth power configuration to ensure highest setting

Version 1.25 05-Dec-2021

Removed Bluetooth power configuration after finding it was not needed Bluetooth connection test now based on BTA rather than ID

Version 1.29 08-Dec-2021

Timing and command strings adjusted to allow for more connection time

Version 1.31 09-Dec-2021

Timing for Bluetooth connection optimized

Version 1.32 16-Feb-2022

Dual tech occupancy sensor monitor and PIR configuration tool added Note: Dual tech support hidden until a right click on an open area of the main screen

Version 1.33 16-Dec-2022

Wireless tools incorporated into one tools package Setup program created

Version 1.34 23-Jan-2023

Display show dimmer values for wireless relays Silicon Labs USB drivers removed from setup program

Version 1.35 29-Jan-2023

Added Discover Network Panel Addresses function

Version 1.36 20-Jul-2023

Added DT ceiling sensor tool

Version 1.37 23-Aug-2023

DT ceiling sensor tool screen uses default settings each time window is opened

Version 1.38 24-Aug-2023

On DT sensor screen

-Changed PIR and acoustic sensitivity order from Low/Mid/High to Low/High/Mid

-Added device configuration options

Version 1.39 11-Oct-2023

Wireless tools removed and new setup program created

Version 1.45 02-Nov-2023

Added DT wall sensor configuration screen

Changed occupancy sensor setting order from low/high/mid to low/mid/high

Removed motor devices

Scan changes in DT Ceiling Sensor screen

Version 1.46 20-Jan-2024

Added hidden profile TX option on Scan Panel Level LightSync Devices screen

Version 1.47 29-Apr-2024

Updated DT ceiling and wall sensor screens for OTW or static settings

Version 1.48 26-Oct-2024

Added hidden TX RTC to local scan

Fixed "divide" typo

Added G3 configuration 1D / MZD-2 two button

Version 1.49 Not released / No beta

(This will be included in next update)

Changed counters from integer to long on local and network scan screens (>32,767 faults caused program crash)

Version 1.50 04-Mar-2025

Embedded conditional input module test/configure functions

Added input to multi-profile mapping tool for conditional input module

Added CSV Export function under file menu on multi-profile mapping tool

Embedded Protocessor mapped gateway functions

Embedded DMX mapped gateway functions

Note: Separate applications for the conditional input module, Protocessor mapped gateway, and DMX mapped gateway are now obsolete and will not be updated.

Version 1.51 23-May-2025

Increased timeout for dimmer devices from 25 to 30 ms

Version 1.52 31-May-2025

On Scan Panel Level screen

Added dimmer level status indicators

Advanced control screen opens by right <shift> clicking in upper left corner

- -Dimmer command strings are displayed
- -Option for LightSync or WLI mode
- -Variable fade rate option
- -TX profile number to local LightSync channel (used to test MP touch screens)
- -TX clock to local LightSync channel (used to test touch screen time/date display)

Version 1.53 04-Jun-2025

On Custom Condition Input edit screen

Added input copy / paste feature

Replaced dropdown combo with selector box for segment edit

Version 1.54 08-Jun-2025

Added relay All Off/All On buttons on local scan screen

Version 1.55 11-Jul-2025

Rearranged advanced options on local scan screen for laptop resolutions Added relay cycle test function to scan panel level screen