

ILC LightLEEDer Tools

- Version 1.21 26-Oct-2020
Bluetooth configuration and test functions added to G3 configure/test screen
- Version 1.22 04-Dec-2020
Bluetooth configuration tool modified due to a configuration failed error
- Version 1.23 10-Dec-2020
Modifications for updated Windows 10 USB port driver timing
- Version 1.24 01-Dec-2021
Added Bluetooth power configuration to ensure highest setting
- Version 1.25 05-Dec-2021
Removed Bluetooth power configuration after finding it was not needed
Bluetooth connection test now based on BTA rather than ID
- Version 1.29 08-Dec-2021
Timing and command strings adjusted to allow for more connection time
- Version 1.31 09-Dec-2021
Timing for Bluetooth connection optimized
- Version 1.32 16-Feb-2022
Dual tech occupancy sensor monitor and PIR configuration tool added
Note: Dual tech support hidden until a right click on an open area of the main screen
- Version 1.33 16-Dec-2022
Wireless tools incorporated into one tools package
Setup program created
- Version 1.34 23-Jan-2023
Display show dimmer values for wireless relays
Silicon Labs USB drivers removed from setup program
- Version 1.35 29-Jan-2023
Added Discover Network Panel Addresses function
- Version 1.36 20-Jul-2023
Added DT ceiling sensor tool
- Version 1.37 23-Aug-2023
DT ceiling sensor tool screen uses default settings each time window is opened
- Version 1.38 24-Aug-2023
On DT sensor screen
-Changed PIR and acoustic sensitivity order from Low/Mid/High to Low/High/Mid
-Added device configuration options
- Version 1.39 11-Oct-2023
Wireless tools removed and new setup program created

Version 1.45 02-Nov-2023

- Added DT wall sensor configuration screen
- Changed occupancy sensor setting order from low/high/mid to low/mid/high
- Removed motor devices
- Scan changes in DT Ceiling Sensor screen

Version 1.46 20-Jan-2024

- Added hidden profile TX option on Scan Panel Level LightSync Devices screen

Version 1.47 29-Apr-2024

- Updated DT ceiling and wall sensor screens for OTW or static settings

Version 1.48 26-Oct-2024

- Added hidden TX RTC to local scan
- Fixed “divide” typo
- Added G3 configuration 1D / MZD-2 two button

Version 1.49 Not released / No beta

- (This will be included in next update)
- Changed counters from integer to long on local and network scan screens (>32,767 faults caused program crash)

Version 1.50 04-Mar-2025

- Embedded conditional input module test/configure functions
- Added input to multi-profile mapping tool for conditional input module
- Added CSV Export function under file menu on multi-profile mapping tool
- Embedded Processor mapped gateway functions
- Embedded DMX mapped gateway functions
- Note: Separate applications for the conditional input module, Processor mapped gateway, and DMX mapped gateway are now obsolete and will not be updated.

Version 1.51 23-May-2025

- Increased timeout for dimmer devices from 25 to 30 ms

Version 1.52 31-May-2025

- On Scan Panel Level screen
 - Added dimmer level status indicators
 - Advanced control screen opens by right <shift> clicking in upper left corner
 - Dimmer command strings are displayed
 - Option for LightSync or WLI mode
 - Variable fade rate option
 - TX profile number to local LightSync channel (used to test MP touch screens)
 - TX clock to local LightSync channel (used to test touch screen time/date display)

Version 1.53 04-Jun-2025

- On Custom Condition Input edit screen
 - Added input copy / paste feature
 - Replaced dropdown combo with selector box for segment edit

Version 1.54 08-Jun-2025

- Added relay All Off/All On buttons on local scan screen

Version 1.55 11-Jul-2025

Rearranged advanced options on local scan screen for laptop resolutions
Added relay cycle test function to scan panel level screen

Version 1.56 23-Jul-2025

Added delay setting to relay cycle test function

Version 1.57 26-Aug-2025

Removed Discover Network Panel Addresses function