

Release Notes (10.06.07)

v10.06.01 12-Sep-2025

- Added disable delay to diagnostic screen Stop button
- Added report button on diagnostic screen
- MP changes – Demo mode
- Added LL Panel Interlaced dimmer / relay mapping tool
- MP changes – Demo mode
- Fixed “Left Even / Right Odd Numbering - W1 Jumper Must Be Installed”
- Added checkbox to add scene device tools to skip scene capture mapping
- Fixed dimmer status labels being displayed after disconnecting

v10.06.06 20-Aug-2026

- Added tools for Clean Touch switches
- Added “Map relay On” feature in tools for the three scene devices
- Added LightSync Device Overview tool
- Added quick links between Input Options and Configure Dimmers
- Added Clean Touch with selectable options to reconfigure device tool
- Added auto save for recovery when program fails close properly

v 06.07 09-Sep-2026

- Modified setup to match product version as shown in Uninstall Program