

# Release Notes 10.06.15

v10.06.01 12-Sep-2025

Added disable delay to diagnostic screen Stop button

Added report button on diagnostic screens

Changes to EVO MP – Demo mode

- Added copy dimmer/relay on/off levels tool to dimmer/relay control screen
- Added LL Panel Interlaced dimmer / relay mapping tool
- Increased Last Open file list from 10 to 16

EVO MP changes

- Automatic file creation tool
- Base file to profiles copy tools
- Profile number from C0 device shown on Input Status screen
- Virtual keypad enabled while in direct connect mode

Fixed “Left Even / Right Odd Numbering - W1 Jumper Must Be Installed”

Changed system diagnostics from single node poll to command 76

Added checkbox to add scene device tools to skip scene capture mapping

Fixed dimmer status labels being displayed after disconnecting

Fixed direct connection (bypass NC) failure after connection fault

v10.06.14 20-Aug-2026

Added tools for Clean Touch switches

Fixed tree view issue where view changed when a device is added or selected

Added note on connect screen about download changes only after file name change

Added “Map relay On” feature in tools for the three scene devices

Added LightSync Device Overview tool

Added quick links between Input Options and Configure Dimmers

Added Clean Touch with selectable options to reconfigure device tool

New MP programming format

Added combined occupancy mapping to new MP programming format

Fixed Input Status error when direct connected to MP node

(Polling for active profile display changed)

Added highlights to control points with masked MP programming

Input to Relay/Group mapping

Preset mapping

Scene mapping

Combined occupancy mapping

Dimmer settings

Save As includes all multi-profile .MPS files

Added Copy/Paste tool on MP mapping screens

Added MP mapping point to caption on title bar on MP mapping screen

Export to App tool added

v10.06.15 09-Sep-2026

Modified setup to match product version as shown in Uninstall Program